

Product Safety Recall & Rework Notice.

February 15, 2022

Dear Enerpac Distributor/Customer,

We are writing to inform you of a product recall and rework that has been issued for the part numbers listed below.

There is a potential risk that the Kingpin can shear and detach. If such a failure occurs, it could cause significant personal injury and/or property damage. As such a recall and rework has been requested for the cutter assemblies shown below.

Our records indicate that these items were sold to you between March 2019 until the present date. **Effective immediately**, these items must be removed from service, returned to the distributor for rework and will be returned to you quickly at no cost to you for materials, parts, labor and/or shipping and handling. All Product held at the distributor is to be reworked by the distributor only prior to sale.

Item Number
ECSE300B
ECSE300E
EDCH130
EDCH145
EDCH170

If you have any of these items in your inventory or have sold these items to end users, they must be returned and reworked. Please notify your customers of this requirement, bring the materials back to a registered service center / distributor for rework. All materials must be returned to your local Enerpac distributor location.

All rework activities should be using the released service kit, please check with technical service team on the correct kits to be used for each model.

Sincerely,

Mark Boardman.
Enerpac Global Quality Director.